

# RECALL OF KTM 1290 SUPER ADVENTURE MODELS

Valid for all markets

**KTM recalls 1290 SUPER ADVENTURE models of model year 2015 and 2016 to the workshops of authorized KTM dealers in order to review the semi-active shock absorber and update its software.**

KTM market investigations have established that the semi-active shock absorber of the KTM 1290 SUPER ADVENTURE MY2015/2016 could exhibit leakages at the plug. Oil loss may result in damage to the interior of the shock absorber and therefore in functional impairment.

In the course of the check for leakages all suspension control units (SCU) on the vehicles affected are flashed with the latest software version for the shock absorber that constitutes the latest development status.

Customers of affected and already distributed motorcycles are informed by a personal letter and are asked to immediately contact an authorized [KTM dealer](#) to arrange an appointment. In addition, customers can check online in the "[Service](#)" area on the KTM website if their motorcycle is affected by the recall.

The review as well as the software update of the semi-active shock absorber can be carried out by authorized KTM dealers only. This check is a guarantee that is completely free of charge.

[www.ktm.com](http://www.ktm.com)

[media.ktm.com](http://media.ktm.com)

**KTM SPORTMOTORCYCLE GMBH**

Thomas Kuttruf // PR-Manager // Tel.: +43 7742 6000 – 866 // Mobile: +43 664 81 62 490  
Fax: +43 7742 6000 – 5866 // Email: [thomas.kuttruf@ktm.at](mailto:thomas.kuttruf@ktm.at) // [www.ktm.com](http://www.ktm.com)

The KTM logo is displayed in a bold, black, italicized font against a solid orange square background.